

Home > IBM > 00MU053

00MU053 – IBM Fan Dual Rotor 60x60x56 for x3650 M5 - FRU

IBM · COMPONENT

PRODUCT OVERVIEW


00MU053: IBM Fan Dual Rotor 60x60x56 for x3650 M5 - FRU.

IBM Fan Dual Rotor 60x60x56 for x3650 M5 - FRU. Available through authorized enterprise resellers and TPM (Third Party Maintenance) channels. Verify compatibility with your specific system configuration before ordering.

SPECIFICATIONS

Part Number	00MU053
Manufacturer	IBM

COMPONENT DIAGRAM



TYPICAL APPLICATIONS

- Server thermal management and cooling
- Hot-swap fan replacement in production environments
- Redundant cooling for high-availability systems

SUBSTITUTES & CROSS-REFERENCES 2

00KA516 Compatible PARTNER

IBM Fan Dual Rotor 60x60x56 for x3650 M5 - FRU compatible

00FK883 Compatible PARTNER

IBM Fan Dual Rotor 60x60x56 for x3650 M5 - P/N compatible

LIFECYCLE

No lifecycle data available.

THIS PART SUBSTITUTES FOR 2

00FK883 SUBSTITUTE

IBM Fan Dual Rotor 60x60x56 for x3650 M5 - P/N IBM

00KA516 SUBSTITUTE

IBM Fan Dual Rotor 60x60x56 for x3650 M5 - P/N IBM

FREQUENTLY ASKED QUESTIONS

What is 00MU053?

00MU053 is a IBM Fan Dual Rotor 60x60x56 for x3650 M5 - FRU manufactured by IBM.

What parts can replace 00MU053?

There are 2 known substitutes for 00MU053: 00KA516, 00FK883. Substitute compatibility should be verified for your specific system.

✓ PartsTable — the parts reference. Every fact cited to its source.


 PartsTable Design LLC · partstable.com

PartsTable commercial catalog: edition Unified commercial catalog snapshot through 2026-09-28, edition date not on file, retrieved 2026-09-28.