



[Home](#) > [Lenovo](#) > 03X3621

03X3621 – Storage Datasheet

LENOVO · DRIVE LFF

WHAT YOU NEED TO KNOW

SAS backplane supports SATA, not vice versa NL-SAS = SAS protocol at nearline (7.2K) speed
— NOT SATA

⚠ Gen8 LFF tray ≠ Gen10 tray — different screw holes

PRODUCT OVERVIEW

IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer RD230/TD230 - Option. The unit ships in a LFF form factor suitable for standard rack-mount installations. Available through authorized enterprise resellers and TPM (Third Party Maintenance) channels.

Verify compatibility with your specific system configuration before ordering.

WHERE IT FITS

LFF BAY



03X3621

SPECIFICATIONS


Part Number	03X3621
Manufacturer	LENOVO
Form Factor	LFF
Capacity	300GB
Speed	15K RPM

FITS THESE MACHINES

[Lenovo ThinkServer RD230](#)

Lenovo ThinkServer TD230

COMPONENT DIAGRAM



KEY FEATURES

- LFF Form Factor
- 300GB Capacity
- 15K RPM Speed

TYPICAL APPLICATIONS

- Enterprise storage arrays and SANs
- Direct-attached storage (DAS) expansion
- Database tier storage (OLTP, OLAP)
- Virtual machine datastore expansion
- Backup-to-disk and disaster recovery targets
- Content delivery and media streaming storage

SUBSTITUTES & CROSS-REFERENCES
 3

67Y1437
Compatible
PARTNER
 IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer RD230/TD230 - Option compatible

46U3259
Compatible
PARTNER
 IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer RD230/TD230 - P/N compatible

46U3572
Compatible
PARTNER
 IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer RD230/TD230 - FRU compatible

LIFECYCLE

No lifecycle data available.

THIS PART SUBSTITUTES FOR 3

46U3259 SUBSTITUTE

IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer - FRU P/N
LENOVO

46U3572 SUBSTITUTE

IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer - FRU P/N
LENOVO

67Y1437 SUBSTITUTE

IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer - FRU P/N
LENOVO

FREQUENTLY ASKED QUESTIONS

What is 03X3621?

03X3621 is a IBM 300Gb SAS 6G 15K LFF HDD for ThinkServer RD230/TD230 - Option manufactured by LENOVO.

What parts can replace 03X3621?

There are 3 known substitutes for 03X3621: 67Y1437, 46U3259, 46U3572. Substitute compatibility should be verified for your specific system.

Is 03X3621 still available?

03X3621 is currently Unknown.

✓ PartsTable — the parts reference. Every fact cited to its source.

 PartsTable Design LLC · partstable.com

PartsTable commercial catalog: edition Unified commercial catalog snapshot through 2026-09-28, edition date not on file, retrieved 2026-09-28.