PartsTable TECHNICAL DATA SHEET

443384-001 — HP PSU 595W for MSA2000/P2000 G2/G3

HPE · PSU

PRODUCT OVERVIEW

443384-001: HP PSU 595W for MSA2000/P2000 G2/G3.

HP PSU 595W for MSA2000/P2000 G2/G3. Available through authorized enterprise resellers and TPM (Third Party Maintenance) channels. Verify compatibility with your specific system configuration before ordering.

SPECIFICATIONS

Wattage	595W

MORE FROM HPE

Popular HPE machine pages — browsing only, not a fit claim for 443384-001.

ProLiant DL360 Gen10 · ProLiant DL380 Gen10 · ProLiant BL460c Gen10 · ProLiant DL380 Gen9 · ProLiant DL360 Gen9 · 3PAR StoreServ 8450 · ProLiant BL685c G7 · 3PAR StoreServ 8400 · 3PAR StoreServ 8440 · 3PAR StoreServ 8200 · MSA 2052 SAN Storage · ProLiant BL460c Gen9

All HPE machines and parts

COMPONENT DIAGRAM



KEY FEATURES

- **595W Power Rating**
- **Generation 2 Platform**

TYPICAL APPLICATIONS

- Server power supply replacement (failed or degraded)
- Redundant power upgrade for high-availability
- Power capacity upgrade for GPU or expansion configurations
- Hot-swap power maintenance in production environments
- Spare inventory for break-fix operations

SUBSTITUTES & CROSS-REFERENCES 12

481320-001 Compatible PARTNER
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves compatible

81-00000031 Compatible PARTNER
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves compatible

CP-1391R2 Compatible PARTNER
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves compatible

YM-2751B Compatible PARTNER
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves compatible

592267-002 Compatible PARTNER
HP PSU 595W for MSA2000/P2000 G2/G3 compatible

7001540-J000 Compatible PARTNER

LIFECYCLE

No lifecycle data available.

HP PSU 595W for MSA2000/P2000 G2/G3
compatible

THIS PART SUBSTITUTES FOR 4

CP-1391R2 SUBSTITUTE
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves
HPE

YM-2751B SUBSTITUTE
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves
HPE

481320-001 SUBSTITUTE
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves
HPE

81-00000031 SUBSTITUTE
HP PSU 595W for MSA2000 G1/G2/VLS9000 Shelves
HPE

FREQUENTLY ASKED QUESTIONS

What is 443384-001?

443384-001 is a HP PSU 595W for MSA2000/P2000 G2/G3 manufactured by HPE.

What parts can replace 443384-001?

There are 12 known substitutes for 443384-001: 481320-001, 81-00000031, CP-1391R2 and 9 more. Substitute compatibility should be verified for your specific system.

✓ PartsTable — the parts reference. Every fact cited to its source.

PartsTable Design LLC · partstable.com

PartsTable commercial catalog: edition Unified commercial catalog snapshot through 2026-09-28, edition date not on file, retrieved 2026-09-28.