

Home > HPE > Server Memory (RAM) > 700757-001

700757-001 – Memory Specs & Substitutes

HP · MEMORY · RDIMM

WHAT YOU NEED TO KNOW

Memory is a hot market right now. DDR5 and DDR4 are extremely volatile with data centers driving availability to extreme lows. Always validate machine type and model. Remember: all RAM is Hynix, Samsung, or Micron underneath OEM labels — use that to find alternatives. Key checks: Double-check what you're quoting in volatile market.

⚠ HOT market — DDR5/DDR4 extremely volatile

PRODUCT OVERVIEW

HP FlexFabric 10Gb 2P 533FLR-T Adptr. Key specifications include Chipset: Broadcom BCM57810S, Internal: Yes, Interface: Ethernet, Full duplex: Yes, Ethernet LAN: Yes, Flash memory: 256 MB. Available through authorized enterprise resellers and TPM (Third Party Maintenance) channels.

Verify compatibility with your specific system configuration before ordering.

WHERE IT FITS



SPECIFICATIONS

Chipset	Broadcom BCM57810S
Internal	Yes
Interface	Ethernet
Full duplex	Yes
Ethernet LAN	Yes
Flash memory	256 MB


Host interface	PCI
Networking standards	IEEE 802.1Q, IEEE 802.3, IEEE 802.3ad, IEEE 802.3x
PCI Card form factor	Full-height (low-profile)
Compliance certificates	RoHS
Connectivity technology	Wired
Ethernet LAN data rates	10,100,1000,10000 Mbit/s

FITS THESE MACHINES

HPE ProLiant DL360 Gen9

HPE ProLiant DL380 Gen9

COMPONENT DIAGRAM



KEY FEATURES

- Yes
- 10GB Capacity

SUBSTITUTES & CROSS-REFERENCES
3

700759B21
Substitute
BROKER-VERIFIED

LIFECYCLE

No lifecycle data available.

HP FlexFabric 10Gb 2P 533FLR-T Adptr substitute

701534-001
Compatible
PARTNER

HP NIC 533FLR-T 10GbE RJ-45 2-Port PCI-E-2.0x8 FlexFabric FlexibleLOM (Broadcom BCM57810S) compatible

700760-B21
Compatible
PARTNER

HP NIC 533FLR-T 10GbE RJ-45 2-Port PCI-E-2.0x8 FlexFabric FlexibleLOM (Broadcom BCM57810S) FIO compatible

THIS PART SUBSTITUTES FOR
 3

700759-B21
SUBSTITUTE

HP NIC 533FLR-T 10GbE RJ-45 2-Port PCI-E-2.0x8 FlexFabric FlexibleLOM (Broadcom BCM57810S) HPE

700760-B21
SUBSTITUTE

HP NIC 533FLR-T 10GbE RJ-45 2-Port PCI-E-2.0x8 FlexFabric FlexibleLOM (Broadcom BCM57810S) HPE

701534-001
SUBSTITUTE

HP NIC 533FLR-T 10GbE RJ-45 2-Port PCI-E-2.0x8 FlexFabric FlexibleLOM (Broadcom BCM57810S) HPE

FREQUENTLY ASKED QUESTIONS

What is 700757-001?

700757-001 is a HP FlexFabric 10Gb 2P 533FLR-T Adptr manufactured by HP. It is classified as a MEMORY (RDIMM).

What parts can replace 700757-001?

There are 3 known substitutes for 700757-001: 700759B21, 701534-001, 700760-B21. Substitute compatibility should be verified for your specific system.

✓ PartsTable — the parts reference. Every fact cited to its source.


 PartsTable Design LLC · partstable.com

PartsTable commercial catalog: edition Unified commercial catalog snapshot through 2026-09-28, edition date not on file, retrieved 2026-09-28.