

Home > HPE > Network Hardware > 766488-001

766488-001 – Network Technical Data

HP · NETWORK · 10GBE_NIC

WHAT YOU NEED TO KNOW

RJ45 = copper (needs CAT6) | SFP+ = fiber (needs transceiver) FLR = FlexibleLOM (HPE integrated) — NOT standard PCIe

⚠ Bracket height **MUST** match chassis — Full Height (2U) vs Low Profile (1U)

PRODUCT OVERVIEW

HP FLEXFABRIC 10GB 2-PORT 536FLB ADAPTER

HP FLEXFABRIC 10GB 2-PORT 536FLB ADAPTER. Available through authorized enterprise resellers and TPM (Third Party Maintenance) channels. Verify compatibility with your specific system configuration before ordering.

WHERE IT FITS



SPECIFICATIONS


Part Number	766488-001
Manufacturer	HP
Capacity	10GB

BROWSE HPE MACHINES

- ProLiant DL360 Gen10
- ProLiant DL380 Gen10
- ProLiant BL460c Gen10
- ProLiant DL380 Gen9
- ProLiant DL360 Gen9
- 3PAR StoreServ 8450
- ProLiant BL685c G7
- 3PAR StoreServ 8400
- 3PAR StoreServ 8440
- 3PAR StoreServ 8200
- MSA 2052 SAN Storage
- ProLiant BL460c Gen9

[All HPE machines and parts](#)

COMPONENT DIAGRAM



KEY FEATURES

- 10GB Capacity

SUBSTITUTES & CROSS-REFERENCES
3

768080001
Substitute
BROKER-VERIFIED
 HP FlexFabric 10GB 2-Port 536FLB Adapter substitute

766490B21
Substitute
BROKER-VERIFIED
 HP FlexFabric 10GB 2-Port 536FLB Adapter substitute

766491-B21
Compatible
PARTNER
 HP NIC 536FLR-SFP+ 10GbE 2-Port PCI-E-3.0x8 FlexFabric FlexibleLOM (QLogic 57840S) FIO compatible

LIFECYCLE

No lifecycle data available.

THIS PART SUBSTITUTES FOR
3

766490-B21
SUBSTITUTE
 HP NIC 536FLR-SFP+ 10GbE 2-Port PCI-E-3.0x8 FlexFabric FlexibleLOM (QLogic 57840S) HPE

766491-B21
SUBSTITUTE
 HP NIC 536FLR-SFP+ 10GbE 2-Port PCI-E-3.0x8 FlexFabric FlexibleLOM (QLogic 57840S) HPE

768080-001 SUBSTITUTE

HP NIC 536FLR-SFP+ 10GbE 2-Port PCI-E-3.0x8 FlexFabric FlexibleLOM (QLogic 57840S)
HPE

FREQUENTLY ASKED QUESTIONS

What is 766488-001?

766488-001 is a HP FlexFabric 10GB 2-Port 536FLB Adapter manufactured by HP. It is classified as a NETWORK (10GBE_NIC).

What parts can replace 766488-001?

There are 3 known substitutes for 766488-001: 7680800001, 766490B21, 766491-B21. Substitute compatibility should be verified for your specific system.

✓ PartsTable — the parts reference. Every fact cited to its source.

 PartsTable Design LLC · partstable.com

PartsTable commercial catalog: edition Unified commercial catalog snapshot through 2026-09-28, edition date not on file, retrieved 2026-09-28.