PartsTable TECHNICAL DATA SHEET

P58221001 — Storage Datasheet

HP · TRANSCEIVER · POWER_CABLE

WHAT YOU NEED TO KNOW

SAS backplane supports SATA, not vice versa NL-SAS = SAS protocol at nearline (7.2K) speed — NOT SATA

⚠ Gen8 LFF tray ≠ Gen10 tray — different screw holes

PRODUCT OVERVIEW

HP DL380 G10P LFF B1 2 7 CABLE KIT

HP DL380 G10P LFF B1 2 7 CABLE KIT. Key specifications include Form Factor: 2U Rack, Platform: HPE ProLiant DL380. The unit ships in a LFF form factor suitable for standard rack-mount installations.

Available through authorized enterprise resellers and TPM (Third Party Maintenance) channels. Verify compatibility with your specific system configuration before ordering.

WHERE IT FITS

TRANSCEIVER → POWER_CABLE → LFF BAY → P58221001

SPECIFICATIONS

Form Factor	2U Rack
Platform	HPE ProLiant DL380

FITS THESE MACHINES

HPE ProLiant DL380 Gen10

COMPONENT DIAGRAM



KEY FEATURES

- **LFF Form Factor**
- **Generation 10 Platform**

TYPICAL APPLICATIONS

- Server Internal Cabling
- Data Center Cable Infrastructure
- SAS/SATA Drive Connectivity

SUBSTITUTES & CROSS-REFERENCES 1

P55467B21 Substitute BROKER-VERIFIED
HP DL380 G10p LFF B1 2 7 Cable Kit substitute

LIFECYCLE

No lifecycle data available.

FREQUENTLY ASKED QUESTIONS

What is P58221001?

P58221001 is a HP DL380 G10p LFF B1 2 7 Cable Kit manufactured by HP. It is classified as a TRANSCEIVER (POWER_CABLE).

What parts can replace P58221001?

There is 1 known substitute for P58221001: P55467B21. Substitute compatibility should be verified for your specific system.

Is P58221001 still available?

P58221001 is currently Unknown.

✓ PartsTable — the parts reference. Every fact cited to its source.

PartsTable Design LLC · partstable.com

PartsTable commercial catalog: edition Unified commercial catalog snapshot through 2026-09-28, edition date not on file, retrieved 2026-09-28.